

Air Hoses


Distribution Box/Change-Over Switch



3/4" 1" 2" 4" Air Hoses



3/4" / 1" Air Hose




2" / 4" Air Hose

Specifications

Diameter	Length	Max working Pressure
3/4"	20m	20bar
1"	20m	20bar
2"	10m	225psi
4"	10m	225psi

DB / Manual Change Over Switches / Step Down Transformer / Extension Wire / Welding Cable

Distribution Box




Three-phase and a Single phase.

Specifications

Rated voltage	No.of Phase	Frequency
400V	3phase	50Hz
230V	1phase	50Hz

Step-Down Transformer -POWER SUPPLY



Specifications

Capacity	Input→Output
1000VA	230VAC→110VAC
	230VAC→24V

Manual Change Over Switch




Specifications

Manual Change Over Switch
80amp
160amp
250amp
370amp
400amp
630amp
800amp
1000amp

Extension Wire



Welding Cable



Length	
Holder 15m	for 300Amp, 400Amp, 500Amp
Earth Clamp 10m	for 300Amp, 400Amp, 500Amp